




The MITO™ 5/MITO™ 6



PARTS CATALOG

MODEL #H519000
MODEL #H520000
MODEL #H522000
MODEL #H523000
ISSUE DATE: 10/96
CATALOG #K243000


Discharge Plumbing (Mito 5)	_____	1
Discharge Plumbing (Mito 6)	_____	2
Suction Plumbing (Mito 5/Mito 6)	_____	3
Air Line Piping (Mito 5)	_____	4
Air Line Piping (Mito 6)	_____	5

See General Bath Parts Catalog for information on the following:

- J-PUMP/MOTOR ASSEMBLY
- OTHER ITEMS AVAILABLE
- FAUCET VALVE
- HTC JET ASSEMBLY
- SUCTION FITTING/COVER ASSEMBLY
- 3-POSITION CONTROL PANEL
- DRAIN/OVERFLOW
- BMH JET ASSEMBLY

TO ORDER

Order by part number unless otherwise noted. Quantities shown in this catalog indicate the number of items required. When ordering, specify the quantity needed.






MITO

MODEL #H519000
 MODEL #H520000
 MODEL #H522000
 MODEL #H523000
 ISSUE DATE: 10/96

DISCHARGE PLUMBING - MITO 5

NOTE: RH discharge plumbing configuration shown.

*See General Bath Parts Catalog



ITEM	P/N	DESCRIPTION	QTY
1	9250000	Repair Kit, Union Adapter	1
2	9231000	O-Ring, Union	1
3	2949000	Tee, Rdcng, 1 1/2 x 1 1/2 x 2	1
4	0167000	Tee, 1 1/2, S x S x S	2
5	D189000	Tee, Rdcng, 1 1/2 x 1 1/2 x 3/4, S x S x S	2
6	D221000	Ell, 3/4, 90, S x S	2
7	0239000	Ell, 90, 1 1/2, S x S	2




MITO

MODEL #H519000
 MODEL #H520000
 MODEL #H522000
 MODEL #H523000
 ISSUE DATE: 10/96

DISCHARGE PLUMBING - MITO 6

NOTE: LH discharge plumbing configuration shown.

*See General Bath Parts Catalog



ITEM	P/N	DESCRIPTION	QTY
1	9250000	Repair Kit, Union Adapter	1
2	9231000	O-Ring, Union	1
3	2949000	Tee, Rdcng, 1 1/2" x 1 1/2" x 2"	1
4	0239000	Ell, 90, 1 1/2" S x S	2
5	D189000	Tee, Rdcng, 1 1/2" x 1 1/2" x 3/4", S x S x S	2
6	D221000	Ell, 3/4, 90, S x S	2
	0167000	Tee, 1 1/2", S x S x S	




MITO

MODEL #H519000
 MODEL #H520000
 MODEL #H522000
 MODEL #H523000
 ISSUE DATE: 10/96

SUCTION PLUMBING - MITO 5/MITO 6

NOTE: RH suction plumbing configuration shown.

*See General Bath Parts Catalog



ITEM	P/N	DESCRIPTION	QTY
1	9250000	Repair Kit, Union Adapter	1
2	9231000	O-Ring, Union	1
3	0851000	Coupling, 2" S x S	2
4	0426000	El, 90, 2" S x S	2




MITO

MODEL #H519000
 MODEL #H520000
 MODEL #H522000
 MODEL #H523000
 ISSUE DATE: 10/96

AIR LINE PIPING - MITO 5

NOTE: RH air line configuration shown.

*See General Bath Parts Catalog



ITEM	P/N	DESCRIPTION	QTY
1	0647000	Coupling, 1/2" S x S	1
2	0455000	Tee, 1/2" S x S x S	4
3	7164000	El, Street, 1/2" 90	3
4	C279000	Adapter, 1/2" S x SPGT	4
5	B777000	Plug, 1/2" SPIG	4




MITO

MODEL #H519000
 MODEL #H520000
 MODEL #H522000
 MODEL #H523000
 ISSUE DATE: 10/96

AIR LINE PIPING - MITO 6

NOTE: LH air line configuration shown.

*See General Bath Parts Catalog



ITEM	P/N	DESCRIPTION	QTY
1	0455000	Tee, 1/2" S x S x S	4
2	C279000	Adapter, 1/2" S x S x S	4
3	0647000	Coupling, 1/2" S x S	1
4	7164000	El, Street, 1/2" 90	1
5		Plug, 1/2" SPIG	1

PRODUCT SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE.
USE INSTALLATION INSTRUCTIONS SUPPLIED WITH PRODUCT.

Jacuzzi Whirlpool Bath has obtained applicable code (standards) listings generally available on a national basis for products of this type. It is the responsibility of the installer/owner to determine specific local code compliance prior to installation of the product. Jacuzzi Whirlpool Bath makes no representation or warranty regarding, and will not be responsible for any code compliance.

JACUZZI WHIRLPOOL BATH

Jacuzzi Whirlpool Bath National Headquarters
P.O. Drawer J, Walnut Creek, CA 94596 (510) 938-7070
Service Support: (800) 288-4002

©Copyright 1996 Jacuzzi Whirlpool Bath K243000 10/96

Printed in the U.S.A.